

SAND REPORT

SAND2004-4083
Unlimited Release
Printed August 2004

Failure Analysis and Surety Design of Composite Patching Systems

Dr. Sameer Hamoush)

Prepared by
Sandia National Laboratories
Albuquerque, New Mexico 87185 and Livermore, California 94550

Sandia is a multiprogram laboratory operated by Sandia Corporation,
a Lockheed Martin Company, for the United States Department of
Energy under Contract DE-AC04-94AL85000.

Approved for public release; further dissemination unlimited.



Issued by Sandia National Laboratories, operated for the United States Department of Energy by Sandia Corporation.

NOTICE: This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government, nor any agency thereof, nor any of their employees, nor any of their contractors, subcontractors, or their employees, make any warranty, express or implied, or assume any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represent that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government, any agency thereof, or any of their contractors or subcontractors. The views and opinions expressed herein do not necessarily state or reflect those of the United States Government, any agency thereof, or any of their contractors.

Printed in the United States of America. This report has been reproduced directly from the best available copy.

Available to DOE and DOE contractors from

U.S. Department of Energy
Office of Scientific and Technical Information
P.O. Box 62
Oak Ridge, TN 37831

Telephone: (865)576-8401
Facsimile: (865)576-5728
E-Mail: reports@adonis.osti.gov
Online ordering: <http://www.doe.gov/bridge>

Available to the public from

U.S. Department of Commerce
National Technical Information Service
5285 Port Royal Rd
Springfield, VA 22161

Telephone: (800)553-6847
Facsimile: (703)605-6900
E-Mail: orders@ntis.fedworld.gov
Online order: <http://www.ntis.gov/ordering.htm>



SAND2004-4083

**Unlimited Release
Printed August 2004**

Failure Analysis and Surety Design of Composite Patching Systems

Dr. Sameer Hamoush

Civil and Arch. Engineering Department

North Carolina A&T State University

Greensboro, NC 27411

ABSTRACT

This work presents an experimental evaluation of patch repair of solid laminated composites. The study was focused on destructive and nondestructive tests of full-scale repaired panels under static tension loading conditions. The testing program consisted of ten panels: three pristine, three damaged, three repaired and one repaired with mismatched fiber orientation patch. The evaluated panels were (300 mm x 675 mm) in size and consisted of 6-ply $((-60 / 60 / 0)_s)$ quasi-isotropic laminates. The destructive tests were performed by North Carolina A&T State University and the nondestructive tests were performed by Iowa State University using Pulse-echo C-scan, Air coupled TTU and Auto-Tap. Sandia National Laboratories validated the NDT tests by implementing NDE field methods. Based on the evaluation performed in this study, it appears that the patch repair is an effective means in retrofitting damaged solid composite laminates.

Acknowledgements

Authors would like to acknowledge the support by FAA grant number 4-48453 and Sandia National Laboratories grant are also acknowledged for their contribution to this research activity. Also, the support by Center for Nondestructive Evaluation, Airworthiness Assurance Center of Excellence Iowa State University for their contribution in the NDT evaluation is greatly acknowledged. .

Contents

Introduction

6

Specimen Fabrication	7
Test and Test Results	12
Summary	18
References	19

List of Figures

Figure 1. Full Scale panel.	8
Figure 2. Scarfed and Repaired Panels	9
Figure 3 NDT scan of patched panels	10
Figure 4: Locations of Strain Gauges	11
Figure 5a Pristine Panels	12
Figure 5c Damaged Panels	13
Figure 5c Repaired Panels	14
Figure 6: Comparison between strain gauges on the three panel types	15
Figure 7: Failed repaired Specimen	16

List of Tables

Table 1. Results of the Testing Program	17
---	----

Introduction

Patch-repairs of composite structures are relatively new technology. Several reliability and survivability issues remain uncertain. Composite patching systems are attractive, in part, because the lay up of the reinforcing fibers can be optimized to handle the service conditions of aircrafts. However, the design must also anticipate the severe loading conditions that can occur in rough weather or during emergency evasive maneuvers. Proactively appraising the performance of composite patching systems under long-term normal service and short-term abnormal conditions is essential to ensure safety of repaired aircraft sections.

The subject of composite repairs has gained attention in the recent years Wang, (1); Bair (2); Armstrong (3) and Donalson (4). Robson (5) looked into the curing effects on the composite patch. He recommended of adding one more ply when a porous vacuum bag curing is used instead of the autoclaved counterparts. Zimmerman (6) performed a systematic investigation of the geometric effects on composite repairs. The focus of his investigation is to optimize the composite repair design in terms of the staking sequences. Zimmerman (7) presented an experimental evaluation of composite repairs of a glass/vinylester composite material with damage caused by impact loading. The focus of the investigation was on the repair angle. He concluded in his investigation that a bond line angle greater than 60° can restore the undamaged composite strength. Heslehurst (8) provided 10-step guide to achieve a successful composite repairs. His techniques addressed the various schemes of inappropriate and poor repairs. Sung-Hoon (9 and 10) performed experimental study and analytical evaluation to check the effectiveness of techniques used for repairing damaged fiber reinforced composites.

Various parameters were investigated in light on the influence of each parameter on the repairs. The evaluated parameters were scarf angles, the number of external plies, moisture content, test temperature and temperatures applied at the time of repairs. His study provided practical procedures and recommendations for the most effective repairs.

Specimen Fabrication

Figure 1 shows a 6-ply quasi-isotropic laminated panel selected for this study. The selected configuration allows a reasonable panel thickness for repair and provides reasonable over all panel size that can be tested in the laboratory. The challenge in the full-scale testing is designing the grips that provide uniform stress distribution across the panel section. Three solid laminates were tested to validate the grip design and evaluate the strain along the mid-section. Panels were dented at the central point to present a damage zone. The damage area was removed according to Boeing design manual and three specimens were tested to evaluate the residual strength of the damaged panels. Scarfing was performed on four additional damaged panels and patch repairs were applied. The scarfing was performed on one side of the panel with 12.5 mm steps. Figure 2a shows the scarfed laminated panel that was performed layer by layer and Figure 2.b shows the repaired panels after the application of the patch. The retained strength was also evaluated by testing four repaired panels in which one panel was repaired with wrong plies orientations. All repairs performed in this program complied with Boeing Standards.

The repaired panels were shipped to Iowa State University's Center for Nondestructive Evaluation Airworthiness Assurance Center of Excellence for NDT evaluation that is to ensure the soundness of the repair. The NDT C-scan is shown in Figure 3. The images shown in Figure 3 indicate good repairs without any apparent flaws.




Figure 1. Full Scale panel.




Figure 2.a Scarfed panels (# 21 and 22)





Figure 2.b Repaired panels

Figure 2. Scarfed and Repaired Panels

Pulse-echo C-scan of Panel 7 - B&W Images

15 MHz Probe: 1/2" diameter, 3" focal length



Pulse-echo C-scan of Panel 7 - Color Images

15 MHz Probe: 1/2" diameter, 3" focal length






Figure 3 NDT scan of patched panels

Strain Gauges were mounted on tested panels at different locations of interest.

Schematic diagrams for the strain gauges locations on one pristine panel, one damaged and one repaired panel are shown on Figure 4.



Undamaged (Pristine Panel)



Damaged Panel (1" centered hole)




Figure 4: Locations of Strain Gauges

Test and Test Results

Load stroke controlled MTS machine was used to test the specimens. Panels were loaded by 0.5 inch stroke displacement/min. The strain and the load were recorded continuously using Vishay's system 5000 data acquisition system for all strain Gauges shown in Figure 4.




Figure 5a Pristine Panels




Figure 5b Damaged panels




Figure 5c Repaired Panels

Figure 5: The stress-strain diagrams for the gauges mounted on (a) Pristine panel, (b) damaged panel and (c) repaired panel.




Figure 6: Comparison between strain gauges on the three panel types.

The stress-strain behavior shown in Figure 6 indicates that the patch increases the stiffness of the panel in comparison with the pristine panel.

Figure 7 shows that the failure in the repaired panel took place at mid-section of the specimen.




Figure 7: Failed repaired Specimen.

Table 1 presents the summary of the results obtained by the testing program. The pristine panels failed on an average load of 191 KN at a stress level of 736 MPa. The damaged panels failed on an average load of 82.2 KN on an average stress of 315.8 MPa. The repaired panels failed on an average load level of 172.2 KN (663.2 MPa axial stress). The testing results indicated that the repaired panel's strength is about 90 percent of the pristine panel. Also, the results indicate that the strength of the repaired panels is more than twice of the damaged panels. Table 1 shows also that the patch repair is a superior. The failure load of the wrongly oriented fibers did not

influence the failure loads of the repaired specimen. The failure load of the wrongly applied patch was 147 KN that is within the tolerance of the repaired panels. This should be verified with more testing.

Table 1. Results of the Testing Program

Cat. Number	Test Configuration	Failure Loads (KN)	Failure Stress (MPa)	Average Loads (KN)	Average Stress (MPa)
1	Pristine	161.2*	619*		
2	Pristine	174.4	670		
3	Pristine	208.8	802	<u>191.6</u> **	<u>736</u> **
4	Damaged	77.4	303.6		
5	Damaged	83.5	320.9		
6	Damaged	85.7	329.2	<u>82.2</u>	<u>315.8</u>
7	Repaired	183.5	704.9		
8	Repaired	154.3	592.9		
9	Repaired	180.2	691.9	<u>172.7</u>	<u>663.2</u>
10	Repaired***	147.2	577.4	<u>147.2</u>	<u>577.4</u>

* Premature Failure due to grip slippage.

** Average of two tests (2 and 3).

*** Repaired with wrong ply orientation.

Summary

The objective of this testing program was focused on evaluating the use of scarf repair as a retrofitting technique for upgrading damaged solid composite laminates. The investigated repairs were performed in accordance with the Boeing standards. Based on the test performed in this study, the following can be concluded:

- 1- Scarf repair is an effective retrofitting technique of defected solid composites.
- 2- Repaired panels performed as expected under static tensile testing conditions
- 3- Scarf repair restores about 90 percent of the undamaged Solid composites.

References:

- 1- Wang, H, Chen, X.H.Guo, X.L. Ren, M.F. "Strength investigation of composite honeycomb structures after repair," *Hangkong Xuebao/Acta Aeronautica et Astronautica Sinica*, May 2001, v 22, n 3, p 270-273.
- 2- Bair, D.L., Hudson, P.O., and Ghanimati, G.R. "Analysis and repair of damaged composite laminates," *International SAMPE Symposium and Exhibition*, 1991, v 36, n 2, p 2264-2278..
- 3- Armstrong, Keith B. "Repair of composite structures," *International Journal for the Joining of Materials*, European Institute for the Joining of Materials, Denmark, Dec, 1997, v 9, n 4, , p 130-137.
- 4- Donaldson, S.L., Song, J.Y. and Roy, A.K. "Research issues in the repair of composite structures," *Offshore Technology Conference, Annual Proceedings*, v 3, 1997, 8p Conference: Proceedings of ther 1997 29th Annual Offshore Technology Conference, OTC'97. May 5-8 1997, Part 3 (of 4), Houston, TX, USA.
- 5- Robson, J.E., Matthews, F.L. and Kinloch, A.J. "Strength of composite repair patches. A laminate analysis approach," *Journal of Reinforced Plastics and Composites*, 1992,.v 11, n 7, Jul, p 729-742.
- 6- Zimmerman, Kristin AND Liu, Dahsin "Geometrical parameters in composite repair," *Journal of Composite Materials*, 1995, v 29, n 11, p 1473-1487.
- 7- Zimmerman, K.B. and Liu, D."Experimental investigation of composite repair," *Experimental Mechanics*, Jun 1996, v 36, n 2, p 142-147.
- 8- Heslehurst, R.B. "Challenges in the repair of composite structures - Part 1," *SAMPE Journal*, Sep-Oct, 1997, v 33, n 5, p 11-16.
- 9- Ahn, Sung-Hoon and Springer, George S. "Repair of composite laminates-test results", *Journal of Composite Materials*, Technomic Publ Co Inc, 1998, v 32, n 11, p 1036-1074.
- 10-Ahn, Sung-Hoon and Springer, George S. "Repair of composite laminates-I: Model Source" *Journal of Composite Materials*, 1998, v 32, n 11, p 1076-1114.

Distribution

5	Dr. Sameer Hamoush Civil and Arch. Engineering Department North Carolina A&T State University Greensboro, NC 27411
1	MS 0323 D. Chavez, 01011 LDRD Office
2	MS 0615 D. Roach, 6252
1	MS 0847 P. Wilson, 9120
2	MS 0893 D. Hammerand, 9123
1	MS 0893 J. Pott, 9123
1	MS 0893 File Copy
1	MS 9018 Central Technical Files, 8945-1
2	MS 0899 Technical Library, 9616